Site ID	Locational Identifier	Lead Gooseneck Currently Present?	Current Street Side Service Line Material	Was Street Side Service Line Material Ever Previously Lead?	Street Side Service Line Size	Street Side Service Line Install Date	Current Property Side Service Line Material	Property Side Service Line Size	Property Side Service Line Install Date	Building Type	Point of Entry or Point of Use Treatment Present?	Building Plumbing Material 1	Building Plumbing Material 2	Building Pluming Material Install Date	Comments	Basis of Street Side Material Classification	Was Street Side Material Field Verified?	Date of Street Side Field Verification if Applicable?	Method of Side Field Verification, If Applicable	Basis of Property Side Material Classification	Was Property Side Material Field Verified?	Date of Property Side Field Verification If Applicable	Method of Property Side Field Verification, If Applicable	Notes on Basis of Material Classification
090 0037 00	Pavilion Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2006	NONRES	N	CLS		Unknown	Multiple Park Buildin	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair	
090 0232 11	W2458 Cty Trk S	UNK	P	N	2"	2019	P	1 1/4"	2009	NONRES	Y	C		2019	Belgioioso/Treat	Installed after	Y	2019	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair	
090 0232 11	Parmesan Cty Trk S	UNK	P	N	8"	2018	P	8"	2021	NONRES	Y	O		2021	Belgioioso/Parm	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2021	Visual insp during install or repair	
090 0232 11	Parmesan Cty Trk S	UNK	P	N	2"	2018	P	2"	2021	NONRES	Y	O		2021		Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2021	Visual insp during install or repair	
090 0233 00	W2310 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	UNK	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0234 01	N4257 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0235 00	N4249 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1961		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0236 00	N4235 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1964		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0237 00	W2109 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0238 00	W2115 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0239 00	W2123 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1962		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0240 00	W2124 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0241 00	W2132 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0243 00	W2131 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0245 00	N4131 Duck Creek Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2005		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0245 01	N4125 Duck Creek Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2005		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0245 02	N4126 Duck Creek Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0245 03	N4120 Duck Creek Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0246 00	N4115 Hwy 55	UNK	P	N	1 1/2"	2006 - 2009	P	1"	2007	SF	N	CLS		1952	1" REDUCER INSTALI	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0246 01	N4165 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2011	MF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair	
090 0246 01	N4163 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2011	MF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair	
090 0246 02	W2180 Cty Trk S	UNK	P	N	1"	2006 - 2009	C	1"	2007	SF	N	UNK		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0246 05	W2176 Mallard Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0246 06	W2163 Mallard Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1984		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0246 07	W2170 Mallard Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0246 08	W2171 Mallard Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0247 00	W2130 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0248 00	W2126 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0249 00	N4121 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0249 01	N4131 Hwy 55	UNK	P	N	1"	2006 - 2009	C	1"	2008	NONRES	N	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0250 00	W2120 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0251 00	N4135 Hwy 55	UNK	P	N	1"	2006 - 2009	C	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0252 00	N4145 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	CLS		1950s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair	
090 0253 00	W2134 Cty Trk S	UNK	P	N	1"	2006 - 2009	p	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0255 00	N4149 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1967		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0256 00	N4155 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0258 00	W2116 Cty Trk S	UNK	P	N	1 1/2"	2006 - 2009	P	1 1/2"	2007	NONRES	UNK	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0260 00	W2150 Mallard Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0261 00	W2172 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1956		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0262 00	W2192 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0263 00	W2156 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0263 01	W2155 Mallard Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0264 00	W2143 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	CLS	C	1971		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair	
090 0264 00	W2143 Ludwig St.	UNK	P	N	1"	2006 - 2009	P	1"	2020	SF	N	O		2020	Shed	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair	
090 0265 00	W2162 Mallard Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	UNK	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair	
090 0266 00	N4431 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1974		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0267 01	N4448 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1969		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0267 02	N4460 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0267 03	N4480 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2001		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0267 04	W1715 Emmett Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2008		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0268 00	N4432 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1961		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0268 01	N4426 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1983		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0269 00	N4444 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0270 00	N4418 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0271 00	N4406 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0272 01	N4419 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0272 02	N4393 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1900s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0272 03	N4411 Cty Trk E	UNK	P	N	1"	2022	P	1"	2022	SF	N	C	O	2023	Mike Vandenberg Jr	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2022	Visual insp during install or repair	
090 0274 00	N4330 Cty Trk E	UNK	P	N	2"	2006 - 2009	P	2"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0275 00	N4381 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1953		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0276 01	N4299 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0276 02	N4325 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1973		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0276 03	N4317 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1975		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0276 04	N4345 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0276 06	N4289 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0276 07	N4343 Cty Trk E	UNK	P	N	1 1/2"	2023	P	1"	2023	SF	N	C	O	2023		Installed after	Y	2023	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair	
090 0277 00	N4367 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1962		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	
090 0278 00	N4307 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1966		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair	

090 0279 01	W1777 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 02	W1765 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1966		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 03	W1785 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 05	N4354 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1963		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 06	W1797 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 07	W1784 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1973		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 08	W1796 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	CLS	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 09	N4334 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 10	N4364 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 12	N4372 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0279 19	N4324 Bell Ct.	UNK	P	N	1"	2019	P	1"	2019	SF	N	UNK		2019		Installed after	Y	2019	Visual insp during install or repair	Installed after lead ban	Y	2019	Visual insp during install or repair
090 0280 00	W1764 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0281 00	W1776 Elk Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0286 00	N4326 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0286 01	N4352 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0290 02	N4225 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		1950s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0290 06	N4231 & N4233 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2012	SF	N	UNK		Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 0290 04	W1952 Tralee Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2016	SF	N	UNK		2019		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 0291 00	N4205 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1942		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0292 00	N4211 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0293 00	N4216 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		1961		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0295 01	N4221 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0296 00	N4222 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0297 00	N4226 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0298 00	N4229 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2019	NONRES	N	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2019	Visual insp during install or repair
090 0299 00	N4268 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1955		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0299 01	N4284 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0300 00	N4260 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1957		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0301 00	N4250 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	C	O	1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 0302 00	N4245 Cty Trk E	UNK	P	N	1"	2007 - 2009	P	1"	2007	NONRES	N	UNK		Unknown		Installed after	Y	2007 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0304 00	N4236 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0308 00	N4273 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1910s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0309 00	N4283 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1910s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0326 01	N4494 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1960S		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0327 00	N4498 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0366 04	N4034 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1980		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0366 01	N4026 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0366 02	N4046 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0366 05	N4064 & N4068 Mc Hugh R	UNK	P	N	1"	2022	P	1"	2024	SF	N	C	O	2024	Duplex	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0366 07	N4082 & N4084 Mc Hugh R	UNK	P	N	1"	2022	P	1 1/4"	2022	SF	N	C	O	2023	Duplex	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2022	Visual insp during install or repair
090 0366 08	N4072 & N4074 Mc Hugh R	UNK	P	N	1"	2022	P	1 1/4"	2022	SF	N	C	O	2022	Duplex	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2022	Visual insp during install or repair
090 0367 00	N3950 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1940s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0368 00	N3902 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0372 00	Historical Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	C		2008		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0373 00	N4035 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1969		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0373 01	N4027 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0376 00	N3848 Parkway Lane	UNK	P	N	1"	2006 - 2009	P	1"	2013	NONRES	N	O		2015		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 0377 00	N3809 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0378 00	N3797 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0379 00	Hardball Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	C		2008	Hardball	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0379 02	N3888 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0379 04	W2088 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2007	RES/CC	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0379 05	N3884 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0379 06	W2090 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0380 00	N3898 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1968		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0381 00	W2039 Industrial Dr.	UNK	P	N	1 1/2"	2006 - 2009	P	1 1/2"	2008	NONRES	N	C		2008	Properties TJS	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0381 01	N3766 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	C		2012		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0381 03	N3748 Hwy 55 Ste A	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	C		2009	Multiple Units	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0381 05	N3712 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2015	NONRES	N	UNK		2009	Multiple Units	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 0381 05	N3712 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2014	NONRES	N	UNK		2009	Multiple Units	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 0381 07	N3748 Uni Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0381 08	N3764 Uni Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0381 12	N3759 Uni Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2009	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 0381 13	N3760 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0381 14	N3736 TJ Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2009	NONRES	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 0381 15	N3768 Uni Dr.	UNK	P	N	1 1/2"	2006 - 2009	P	1 1/2"	2011	NONRES	N	UNK		2012	Only lateral size marl	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 0382 00	N3783 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1920s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0386 01	N3800 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0386 02	N3788 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0386 03	N3782 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0389 00	N4021 Cty Trk E	UNK	P	N	4"	2007 - 2009	P	4"	2007	SCH/DC	N	UNK		Unknown		Installed after	Y	2007 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0389 01	N4012 Cty Trk E	UNK	P	N	1"	2008 - 2009	P	1"	2008	NONRES	N	UNK		2008		Installed after	Y	2008 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0389 02	N4006 Cty Trk E	UNK	P	N	2"	2009 - 2009	P	2"	2008	NONRES	N	UNK		2008	SWEET TOOTH	Installed after	Y	2009 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0390 00	N4011 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1965		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0390 01	N4001 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair

090 0392 00	N3985 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1964		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0393 00	W2354 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1983		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0395 02	N3904 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown	FREEDOM FAST WAS	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0396 02	N3964 & N3966 Washingtor	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		2005	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 03	N3980 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2006	NONRES	Y	C		2019		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0396 04	N3946 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	UNK	UNK		2007		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 05	N3936 Washington Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	MF	UNK	UNK		Unknown	APPLE GREEN	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 07	N3972 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0396 08	N3947 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 09	N3994 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown	Mama D's	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0396 11	N3925 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 11	N3929 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 11	N3935 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 13	N3995 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 14	N3943 & N3945 Washingtor	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 15	N3955 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 16	N3965 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 17	N3957 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown	Robert Kern	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 18	N3951 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown	Robert Kern	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 19	N3971 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 22	N3949 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 23	N3979 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 24	N3969 Columbia Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0396 25	N3947 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 26	N3914 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 26	N3918 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 27	N3932 Washington Ave.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown	APPLE GREEN	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0396 30	N3988 & N3990 Washingtor	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0399 00	N4056 Vine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		2007	Belgioioso	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0402 00	N3809 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0402 01	N3799 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0402 02	N3843 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS	O	1972		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0402 03	N3829 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1 1/4"	2008	SF	Y	C	O	1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0402 04	W2326 Malia Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0402 05	W2341 Malia Ln.	UNK	P	N	1"	2021	P	1 1/4"	2021	SF	N	C		2021		Installed after	Y	2021	Visual insp during install or repair	Installed after lead ban	Y	2021	Visual insp during install or repair
090 0402 07	N3813 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1 1/4"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0403 00	N3818 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0405 01	N3781 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0405 02	N3755 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1955		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0407 01	N3782 Country Villa Way	UNK	P	N	8"	2014	P	8"	2014	MF	UNK	UNK		2014	Country Villa 1	Installed after	Y	2014	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 0407 03	Fire Station Schmidt Rd.	UNK	P	N	8"	2020	P	8"	2020	NONRES	Y	C		2020	2 Water Softeners	Installed after	Y	2020	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair
090 0407 04	N3779 Country Villa Way	UNK	P	N	8"	2018	P	8"	2018	MF	UNK	UNK		2019	Country Villa 2	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2018	Visual insp during install or repair
090 0407 21	N3788 & N3790 Wheatfield	UNK	P	N	2"	2018	P	1"	2018	SF	N	C	O	2019	Condo Association	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2018	Visual insp during install or repair
090 0407 23	N3780 & N3782 Wheatfield	UNK	P	N	2"	2018	P	1"	2019	SF	N	C	O	2019	Condo Association	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2019	Visual insp during install or repair
090 0407 25	N3772 & N3774 Wheatfield	UNK	P	N	2"	2018	P	1"	2020	SF	N	C	O	2020	Condo Association	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair
090 0407 27	N3771 & N3773 Wheatfield	UNK	P	N	2"	2018	P	1"	2022	SF	N	C	O	2023	Condo Association	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2022	Visual insp during install or repair
090 0407 29	N3779 & N3781 Wheatfield	UNK	P	N	2"	2018	P	1"	2022	SF	N	C	O	2022	Condo Association	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2022	Visual insp during install or repair
090 0407 31	N3787 & N3789 Wheatfield	UNK	P	N	2"	2018	P	1"	2021	SF	N	C	O	2023	Condo Association	Installed after	Y	2018	Visual insp during install or repair	Installed after lead ban	Y	2021	Visual insp during install or repair
090 0409 00	N3899 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS		1966		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 0410 01	N3887 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2013	NONRES	N	UNK		2013	DOLLAR GENERAL	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 0411 00	N3857 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0411 05	N3856 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1975		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0411 06	N3850 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0411 07	N3844 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1983		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0411 08	N3841 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2015	SF	N	C	O	2014		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 0411 09	N3825 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0411 10	N3826 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0412 00	N3861 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0412 01	N3883 Cty Trk E	UNK	P	N	1"	2020	P	1"	2020	SF	N	UNK		Unknown		Installed after	Y	2020	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair
090 0415 00	N3789 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	C	O	2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 0571 00	N3643 Vine Rd.	UNK	P	N	1 1/4"	2006 - 2009	P	1 1/4"	2008	SF	N	C	O	2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0571 01	N3613 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1975		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0571 03	N3627 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0571 04	N3681 Vine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2013	SF	N	C	O	2013		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 0571 05	N3659 Vine Rd.	UNK	P	N	1 1/4"	2006 - 2009	P	1 1/4"	2008	SF	N	C	O	2001		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0572 00	N3611 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	O		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0573 00	N3641 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1800s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0574 00	N3623 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1950s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0575 00	N3633 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1969		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0577 01	N3545 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1983		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0577 02	N3539 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0579 00	N3548 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1965		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0579 00	N3550 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1965		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0580 00	N3534 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1963		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 00	N3573 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair

090 0581 01	N3527 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 02	N3541 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1971		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 03	N3535 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 04	N3538 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 05	N3551 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1971		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 06	N3528 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1971		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 07	N3503 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 08	N3517 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 09	N3525 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 10	N3531 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 11	N3537 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 12	N3494 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	O	1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 13	N3534 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	2003		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 14	N3533 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS	1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 15	N3510 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	1997		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 17	N3526 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	1986		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 19	N3507 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1 1/4"	2017	SF	N	C	2018		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2017	Visual insp during install or repair
090 0581 20	N3509 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1 1/4"	2017	SF	N	C	2018	CALMES VERKUILEN	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2017	Visual insp during install or repair
090 0581 21	N3511 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2016	SF	N	C	2017		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 0581 22	N3513 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2016		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0581 23	N3502 Hooyman Ct.	UNK	P	N	1"	2017	P	1"	2017	SF	N	C	2018		Installed after	Y	2017	Visual insp during install or repair	Installed after lead ban	Y	2017	Visual insp during install or repair
090 0582 00	N3561 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1966		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0583 00	N3540 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1961		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0584 00	N3521 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1965		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0585 00	N3555 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1966		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0586 00	N3561 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0586 03	N3564 & N3566 Cty Trk E	UNK	P	N	1 1/2"	2006 - 2009	P	1 1/2"	2008	SF	N	UNK	Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0586 04	N3573 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2005		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0587 00	N3584 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1920s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0587 01	N3590 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0587 02	N3572 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1 1/2"	2008	SF	N	C	2007		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0588 00	N3598 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS	1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0589 00	N3569 Cty Trk E	UNK	P	N	4"	2006 - 2009	P	4"	2008	SCH/DC	N	UNK	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0590 00	N3608 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1962		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0592 00	N3539 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0593 00	N3551 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1950s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0600 01	N3495 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0601 00	N3483 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0601 02	N3491 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0601 03	N3479 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2006		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0601 05	N3475 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2016	SF	N	C	2016		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 0607 02	N3475 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2009		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0608 00	N3497 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS	1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0609 00	N3485 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS	1962		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 00	N3468 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 03	N3524 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS	1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 04	N3512 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 06	N3504 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1934		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 06	N3504 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2015	NONRES	N	UNK	1934	Tryba Barn	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 0610 07	N3490 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2009	NONRES	N	UNK	Unknown	Vinton	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 0610 08	N3513 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 09	N3507 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 10	N3506 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	1986		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 11	N3516 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	1997		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 12	N3508 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0610 13	N3510 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0615 01	W2238 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK	1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0619 01	W2377 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS	1918		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0619 02	W2393 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0619 03	W2304 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 04	W2310 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 05	W2318 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 06	W2326 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/2"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 07	W2332 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 08	W2342 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 09	W2371 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 10	W2365 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 11	W2357 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 12	W2341 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 13	W2335 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 14	W2327 Schmidt Rd	UNK	P	N	1 1/4"	2022	P	1 1/2"	2025	SF	N	O		2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 15	W2321 Schmidt Rd.	UNK	P	N	1 1/4"	2022	P	1 1/2"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 16	W2322 Warren Trail	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 17	W2330 Warren Trail	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 18	W2338 Warren Trail	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair

090 0619 19	W2346 Warrant Trail	UNK	P	N	1 1/4"	2022	P	1 1/4"	2025	SF	N	O		2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 20	W2345 Warren Trail	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 21	W2337 Warren Trail	UNK	P	N	1 1/4"	2023	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 22	W2331 Warren Trail	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C		2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 23	W2321 Warren Trail	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 24	N3635 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 25	N3629 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	Y	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 26	N3621 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2025	SF	N			2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 0619 27	N3611 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 28		UNK	P	N	1 1/4"	2022	P			SF	N				Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 0619 29	W2340 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 30	W2348 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/2"	2025	SF	N			2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 31	W2356 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 32	W2360 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 33	W2368 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 34	W2374 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 35	W2380 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	O		2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 36	W2388 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 37	W2396 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 38	W2402 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 39	W2410 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/2"	2024	SF	N	C	O	2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 40	W2418 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/2"	2025	SF	N	O		2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 41	W2430 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 42	W2375 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 43	W2359 Ethan Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 44	W2351 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 45	W2343 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 46	W2335 Ethan Dr.	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 47	W2328 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 48	W2342 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 49	W2348 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2026	SF	N			2026	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 0619 50	W2362 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 51	W2372 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 52	W2373 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/2"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 53		UNK	P	N	1 1/4"	2022	P			SF	N				Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 0619 54		UNK	P	N	1 1/4"	2022	P			SF	N				Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 0619 55		UNK	P	N	1 1/4"	2022	P			SF	N				Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 0619 56	W2333 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 57	W2327 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 58	W2319 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/2"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 59	W2311 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 60	W2303 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 61	W2306 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 62	W2314 Khloe Ln	UNK	P	N	1 1/4"	2022	P	1 1/2"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 63	N3596 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 64	N3604 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 65	N3610 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 66	N3616 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/2"	2025	SF	N	O		2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 67	N3624 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/2"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 68	N3630 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 69	N3638 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/2"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 70	N3644 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/2"	2025	SF	N	O		2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0619 71	N3654 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2024	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2024	Visual insp during install or repair
090 0619 72	N3660 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1"	2023	SF	N	C	O	2023	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 73	N3668 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2023	SF	N	C	O	2024	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2023	Visual insp during install or repair
090 0619 74	W2305 Gavin Dr	UNK	P	N	1 1/4"	2022	P	1 1/4"	2025	SF	N	O	C	2025	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 0620 00	N3670 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2020	SF	N	C	O	2020	Installed after	Y	2022	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair
090 0620 01	N3675 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0620 02	N3662 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1960s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0620 04	N3644 Vine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	C	O	2008	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 0621 00	N3687 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1956	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0622 00	N3679 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1960	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0623 00	N3695 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1975	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0624 01	N3656 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0624 02	W2474 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0624 03	W2468 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1976	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0624 05	N3622 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0625 00	N3602 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1960s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0626 00	N3616 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1964	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0627 00	W2492 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0628 00	W2488 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1950s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 01	N3514 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 02	N3588 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1930s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 03	N3576 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1987	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 05	N3532 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1984	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair

090 0629 06	N3612 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 07	N3578 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 08	N3577 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 09	N3602 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 10	N3570 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1990s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0629 11	N3588 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0630 00	N3596 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	CLS		1955		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 0631 00	N3506 Cty Trk N	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 0998 00	N4106 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	Home Tavern	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 0999 00	N4110 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	Sturm Enterprises	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1000 00	W2022 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2006	NONRES	N	UNK		Unknown	Truckey Properties	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1002 00	N4114 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	NONRES	N	UNK		Unknown	Leap Inn	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1005 00	W2004 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2009	NONRES	N	UNK		Unknown	Town Hall	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1008 00	N4128 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1800s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1009 00	N4134 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1930s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1010 00	N4140 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1011 00	N4144 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1870	Plumbing updated at	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1012 00	N4133 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS		1961		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1014 00	N4121 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1966	Copper post meter, p	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1015 00	N4115 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS		1956		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1017 00	W1990 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C	O	1965		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1018 01	W1980 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	C	O	1800s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1019 00	N4114 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	CLS		1954		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1020 00	N4120 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1950	Copper post meter to	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1021 00	N4124 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1950s	Copper post meter 6	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1022 00	N4128 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1954		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1023 00	N4134 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1954		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1024 00	N4142 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1951		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1025 00	N4148 Coffey St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1957		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1026 00	N4154 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1940s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1027 00	N4164 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1900		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1028 00	W1962 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1890		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1029 00	W1968 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1030 00	W1952 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1924		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1031 00	W1944 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1900s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1032 00	W1928 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1032 01	W1936 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1033 00	W1922 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	UNK	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1034 01	N4108 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1975		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1034 02	N4104 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1034 03	N4114 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	O		1976		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1034 04	N4122 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1035 00	N4107 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1036 00	N4113 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1957		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1037 00	N4103 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Units A & B	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1038 00	N4119 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1965		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1039 00	N4139 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1950s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1040 00	N4167 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1040 01	N4159 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1040 02	N4163 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1041 00	N4145 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1950s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1042 00	N4146 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1968		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1043 00	N4151 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1967		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1044 00	N4193 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1958		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1044 01	N4160 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1044 02	N4170 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1045 00	N4152 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1963		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1046 00	N4170 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1946		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1048 00	Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	CLS	O	1940		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1049 00	N4180 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1921		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1052 00	N4196 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1957		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1053 00	N4202 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1960		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1054 00	N4206 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1953		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1055 01	N4138 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1975		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1055 02	N4130 Peterson Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1056 00	N4172 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1057 00	N4142 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1965		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1060 00	W2060 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1963		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1061 01	W2048 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	Shop & Save Mart	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1063 00	N4111 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	Beavers Hut	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1064 00	N4119 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	C	O	2016		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1065 00	N4125 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1065 00	W2040 Patrick St.	UNK	P	N	1"	2016	P	1"	2016	NONRES	N	UNK		Unknown		Installed after	Y	2016	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 1067 00	N4133 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1927		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1068 00	N4139 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1900s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair

090 1069 00	N4145 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1935		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1070 00	N4153 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1880		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1071 00	N4157 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1962		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1072 00	N4159 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1073 00	N4163 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1960s	Copper 1ft post mete	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1074 00	N4169 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1916	Post meter is all poly	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1075 00	N4173 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1943		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1076 00	N4177 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1943		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1077 00	N4181 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1942		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1078 00	N4185 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS		1945		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1079 00	N4189 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1946	Copper post meter tc	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1080 00	N4193 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1948	Copper post meter tc	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1081 00	N4199 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1951		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1084 00	N4083 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	B's Brews	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1085 00	W2069 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS		100 yrs		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1086 00	W2075 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS		1939		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1087 00	W2081 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS		1954		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1089 00	N4077 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		100 yrs		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1090 00	N4071 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	C	O	100 yrs	updated 2018	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1091 00	N4067 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		100 yrs		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1092 00	N4063 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1930s	Upper & Lower Units	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1093 00	N4059 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1093 01	N4055 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O	C	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1095 00	N4051 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1935		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1096 00	N4047 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1099 00	W1905 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1100 00	W1915 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1957		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1101 00	W1919 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1954		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1102 00	W1927 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS	O	1950		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1103 00	N4079 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1104 02	W1945 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1950		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1105 00	W1947 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1106 00	W1942 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1106 01	W1937 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1106 02	W1934 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1107 00	W1948 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1987		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1107 01	W1949 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS	O	1950		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1108 00	W1961 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1880		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1109 00	W1961 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		2003		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1111 00	W1963 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1112 00	W1973 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1990s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1114 00	W1969 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2014	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 1115 00	W1993 Cty Trk S	UNK	P	N	8"	2006 - 2009	P	8"	2007	MF	UNK	UNK		Unknown	Vandeberg Apts Lena	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1117 00	W2037 Cty Trk S	UNK	P	N	2"	2006 - 2009	P	1"	2007	SCH/DC	UNK	UNK		Unknown	St. Nicks School/Chu	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1118 00	N4086 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		Unknown	Rectory	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1119 00	N4080 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	CLS		1951		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1121 00	N4076 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	C	O	2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1123 00	N4064 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1123 00	N4062 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1125 00	N4060 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1126 01	N4057 Liberty Ln.	UNK	P	N	2"	2006 - 2009	P	2"	2007	MF	N	UNK		Unknown	Tom Muprhy Apts	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1127 00	N4040 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1127 01	N4026 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1127 02	N4014 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1128 00	N4004 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1129 00	N3960 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1129 03	N3986 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1129 05	N3940 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1130 00	N3994 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1131 00	N3936 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1132 00	N3980 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1133 00	N4046 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1133 01	N4039 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1134 00	N3963 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1134 01	N3929 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1134 02	N4003 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1135 00	N4025 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1136 00	N4017 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1137 00	N3993 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1138 00	N3985 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1139 00	N3957 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2012	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 1139 01	N3949 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1140 00	N3975 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1141 00	N3969 Conrad St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1144 00	N4042 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair

090 1147 00	N4022 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1148 00	N4016 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	C	O	1948		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1149 00	N4008 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1154 00	N3996 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1950s	updated 2016	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1155 00	N3984 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1950s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1157 00	N3976 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1989		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1158 00	N3966 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	CLS	O	1951		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1160 00	N3954 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1950		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1161 00	N3944 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1162 00	N3938 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS	O	1950		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1163 00	N3928 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1164 00	VFW Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	VFW	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1165 00	W2082 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	Sal's Foods	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1166 00	N4116 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1167 00	N4124 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1975	Updated 2012	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1169 00	N4113 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1170 00	N4123 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1982	Copper post meter to	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1171 00	N4127 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1975	Plumbing post meter	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1172 00	N4131 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1978	Copper post meter to	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1173 00	N4137 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1174 00	W2087 Patrick St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1175 00	W2089 Patrick St.	UNK	P	N	1"	2006 - 2009	P	1 1/4"	2019	SF	N	O		2019		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2019	Visual insp during install or repair
090 1177 00	W2070 Cty Trk S	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1178 00	N4112 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1974		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1179 00	N4116 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1979		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1181 00	N4124 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1968		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1182 00	N4136 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1183 00	N4144 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1975		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1184 00	N4170 Hwy 55	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1185 00	W2090 Patrick St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1974		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1187 00	W2084 Patrick St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1189 00	N4157 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1190 00	N4163 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1952		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1191 00	N4173 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1192 00	N4183 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1195 00	W2066 Patrick St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1196 00	N4162 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	O		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1197 00	N4168 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1976		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1198 00	N4174 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	O		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1199 00	N4180 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1977	Copper 15ft post me	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1200 00	N4186 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1976		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1202 00	N4148 & N4150 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1203 00	N4158 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1204 00	N4168 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1205 00	N4183 Twin Ct	UNK	P	N	1"	2007 - 2009	P	1"	2007	SF	N	C	O	2025		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1206 00	N4174 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1955		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1208 00	N4184 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1976		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1209 00	N4188 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1210 00	N4194 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1211 00	N4198 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1976		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1212 00	N4204 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1213 00	N4196 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1979	Copper post meter to	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1214 00	N4192 Garvey Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1215 01	N4199 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1216 00	N4167 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1217 00	N4165 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1217 01	N4163 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1218 00	N4159 Twin Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1219 00	W2058 Patrick St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1220 00	W2057 Patrick St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1225 00	N3540 Hooyman Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1226 00	N3543 Bonnie St	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1228 00	W1935 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1229 00	W1943 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1232 00	W1926 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS	O	1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1233 00	W1920 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1234 00	W1912 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1235 00	N4067 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1970s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1236 00	W1913 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1960s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1237 00	W1919 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1238 00	W1925 Vandenberg St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1264 00	W2075 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1265 01	W2067 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1266 00	W2059 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1270 00	W2049 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1977		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair

090 1271 00	W2043 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1272 00	W2037 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1273 00	W2031 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1274 00	W2025 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1275 00	W2017 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1276 00	W2013 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1277 00	W2009 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1278 00	W2005 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1279 00	W2001 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1280 00	W1995 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1281 00	W1991 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1282 00	W1985 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1283 00	W1981 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1284 00	W1979 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1285 00	W1977 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1286 00	W1973 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1287 00	W1967 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1288 00	W1959 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1289 00	W1953 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1290 00	W1947 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	O		1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1291 00	W1939 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1292 00	W1933 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1293 00	W1925 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	CLS		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1294 00	W1917 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	C		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1295 00	W1911 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1296 00	N4003 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1297 00	W2060 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1298 00	W2042 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1299 00	W2036 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1300 00	W2030 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1301 00	W2024 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	CLS	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1302 00	W2016 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1303 00	W1996 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1304 00	W1986 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1305 00	W1968 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1980	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1306 00	W1960 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1307 00	W1954 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1308 00	W1948 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O	C	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1309 00	W1940 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	O		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1310 00	W2074 Vans Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1311 00	N4365 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1312 00	N4371 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1313 00	N4379 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1314 00	N4405 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1315 00	N4409 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1976	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1316 00	N4408 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1317 00	N4404 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1318 00	N4398 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1319 00	N4394 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1320 00	N4388 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1978	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1321 00	N4056 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1322 00	N4050 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1324 00	N4032 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1325 00	N4026 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1326 00	N4020 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1327 00	N4012 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1328 00	N4002 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1329 00	N3996 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1330 00	N3988 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1331 00	N3982 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1332 00	N3974 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1333 00	N3964 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1334 00	N3958 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1335 00	N3950 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1336 00	N3942 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1337 00	N3930 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1338 00	N3922 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1339 00	N3910 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1341 00	N3909 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1342 00	N3917 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1343 00	N3925 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1344 00	N3933 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1345 00	N3949 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1346 00	N3953 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1347 00	N3963 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair

090 1348 00	N3973 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1976	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1349 00	N3981 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1350 00	N3987 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1351 00	N3995 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1352 00	N4003 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1976	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1353 00	N4011 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1354 00	N4019 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1355 00	N4025 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1356 00	N4031 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1357 00	N4047 Liberty Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1358 00	N3872 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1979	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1358 01	N3890 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1359 00	N3860 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1359 01	N3850 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1984	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1360 00	N3836 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1973	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1361 00	N3822 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1362 00	N3802 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	CLS		1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1363 00	N3798 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1364 00	N3796 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		2007	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1365 00	N3786 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2000	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1365 01	N3792 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1366 03	N3734 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1980s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1367 00	N3703 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1977	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1369 00	N3844 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	UNK	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1370 00	N3801 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1975	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1370 01	N3781 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1997	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1370 02	N3787 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1371 01	N3815 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1978	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1372 00	N3889 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1978	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1372 01	N3863 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1978	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1372 02	N3841 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1979	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1373 00	N3879 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1378 01	N3760 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2002	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1379 00	N3740 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1381 00	N3720 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	O	1997	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1382 00	N3712 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1998	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1384 00	N3739 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1384 01	N3749 Sharon Rose Ct.	UNK	P	N	1"	2008	P	1 1/4"	2020	SF	N	C		2021	Installed after	Y	2008	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair
090 1385 00	N3757 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2009	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1385 01	N3755 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1386 00	W2050 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		1985	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1387 00	W2038 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	C		1991	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1388 00	W2024 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	C		1990	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1390 00	W2015 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1391 00	W2027 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1392 00	W2039 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1392 01	W2039 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2008	NONRES	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1395 00	W2093 Industrial Dr.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1396 00	N3997 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1978	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1397 00	N3989 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1507 00	N3977 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1993	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1508 00	N3971 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1974	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1509 00	N3965 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	CLS	O	1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1510 00	N3957 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1511 00	N3951 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1512 00	N3945 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1513 00	N3937 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C	O	1970	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1514 00	N3931 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1981	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1515 00	N3927 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1516 00	N3919 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS		1982	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1517 00	N3911 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS	O	Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1518 00	N3905 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	CLS		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1519 00	N3893 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1987	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1520 01	Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 02	N3972 Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 03	N3964 Deere Drive	UNK	P	N	1"	2025	P	1 1/4"	2025	SF				2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 04	Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 05	Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 06	Deere Drive	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 07	N3938 Deere Drive	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	O		2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 08	Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 09	Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 10	N3920 Deere Drive	UNK	P	N	1"	2025	P	1 1/4"	2026	SF	N	C	O	2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 11	N3914 Deere Drive	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 12	N3908 Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair

090 1520 13	Park Ave	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 14	Park Ave	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 15	Park Ave	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 16	Park Ave	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 17	Park Ave	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 18	Park Ave	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 19	Park Ave	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 20	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 21	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 22	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 23	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 24	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 25	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 26	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 27	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 28	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 29	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 30	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 31	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 32	Olivia Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 33	W1980 & W1982 Olivia Dr	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 34	W1981 & W1983 Tyler Way	UNK	P	N	1"	2025	P	1 1/4"	2026	SF	N	C	O	2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 35	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 36	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 37	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 38	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 39	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 40	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 41		UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 42	N3960 Jean Ann Ct	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 43	Jean Ann Ct	UNK	P	N	1"	2025	P		2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 44	Jean Ann Ct	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 45	Jean Ann Ct	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 46	Jean Ann Ct	UNK	P	N	1"	2025	P		2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 47		UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 48	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 49	Tyler Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 50		UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 51	N3949 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 52	N3950 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF				2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 53	N3954 Wettering Way	UNK	P	N	1"	2025	P	1"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 54	N3958 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 55	N3962 Wettering Way	UNK	P	N	1"	2025	P	1"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 56	N3972 Wettering Way	UNK	P	N	1"	2025	P	1"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 57	N3976 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF				2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 58	Wettering Way	UNK	P	N	1"	2025	P		2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 59	Wettering Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 60	N3975 Deere Drive	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 61	N3969 Deere Drive	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 62	Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 63	Deere Drive	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 64	N3997 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 65	N3991 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 66	N3987 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 67	N3983 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 68	Wettering Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 69	N3975 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	O		2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 70	N3971 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 71	N3967 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C		2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 72	Wettering Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 73		UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 74	W1984 Grode Ct	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 75	Grode Ct	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 76	Grode Ct	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 77	Grode Ct	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 78	W1973 Grode Ct	UNK	P	N	1"	2025	P	1"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 79	N3945 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 80	Wettering Way	UNK	P	N	1"	2025	P			SF					Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 81	N3937 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 82	N3933 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 83	N3927 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 84	N3923 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 85	N3919 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 86	N3913 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 87	N3909 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025	Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair

090 1520 88	N3903 Wettering Way	UNK	P	N	1"	2025	P	1 1/4"	2025	SF	N	C	O	2025		Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 89	W1997 & W1999 Park Ave	UNK	P	N	1"	2025	P	1 1/4"	2026	SF				2026		Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1520 90	W1989 & W1991 Park Ave	UNK	P	N	1"	2025	P	1 1/4"	2025	SF				2025		Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 91	Park Ave	UNK	P	N	1"	2025	P			SF						Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 92	Park Ave	UNK	P	N	1"	2025	P			SF						Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y		Visual insp during install or repair
090 1520 93	Park Ave	UNK	P	N	1"	2025	P	1 1/4"	2025	SF				2025		Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2025	Visual insp during install or repair
090 1520 94	W1957 & W1959 Park Ave	UNK	P	N	1"	2025	P		2026	SF				2026		Installed after	Y	2025	Visual insp during install or repair	Installed after lead ban	Y	2026	Visual insp during install or repair
090 1533 00	N4206 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1984		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1534 00	N4216 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1535 00	N4228 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1983		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1536 00	N4236 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1537 00	N4248 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1538 00	N4260 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1986		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1539 00	N4276 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1983		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1540 00	N4286 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1984		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1541 00	N4294 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1542 00	N4302 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1543 00	N4301 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1544 00	N4295 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1545 00	N4287 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		1980		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1546 00	N4275 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1989		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1547 00	N4261 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1987		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1548 00	N4245 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1549 00	N4233 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1982		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1550 00	N4223 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1990s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1551 00	W2228 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		1982		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1552 00	W2256 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1987		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1553 00	N3956 & N3958 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1989	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1554 00	N3960 & N3962 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1555 00	N3964 Shamrock Circle	UNK	P	N	2"	2006 - 2009	P	2"	2008	MF	UNK	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1556 00	N3959 & N3961 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1557 00	N3951 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1558 00	N3943 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1984		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1559 00	N3939 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1560 00	N3933 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1561 00	N3927 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2010	SF	N	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 1562 00	W2274 Clover Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1984		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1563 00	W2278 Clover Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1564 00	W2277 Clover Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1565 00	W2273 Clover Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1566 00	N3919 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1567 00	N3911 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1997		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1568 00	N3903 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1987		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1569 00	N3885 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1570 00	N3882 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1987		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1571 00	N3886 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1572 00	N3892 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1989		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1573 00	N3898 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1983		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1574 00	N3904 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1985		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1575 00	N3908 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	O	1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1576 00	N3912 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1577 00	N3918 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	O	1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1578 00	N3922 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1579 00	N3926 & N3928 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1987	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1580 00	N3932 & N3934 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1581 00	N3940 & N3942 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1582 00	W2257 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1583 00	W1889 & W1891 Kaye St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1997	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1584 00	W1890 Kaye St.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1987		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1585 00	N4252 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1586 00	N4260 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1587 00	N4264 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1997		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1588 00	N4270 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1589 00	N4278 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1590 00	W1863 Van Asten Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1591 00	W1855 Van Asten Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1592 00	W1843 Van Asten Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1593 00	W1831 Van Asten Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1594 00	W1823 Van Asten Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1595 00	W1815 Van Asten Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1989		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1597 00	W1797 Van Asten Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1598 00	W2238 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1599 00	N4220 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1600 00	N4230 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS		1986		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1601 00	N4240 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair

090 1602 00	N4244 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1603 00	N4239 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1604 00	N4231 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1605 00	N4221 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1606 00	N4211 Maple Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1607 00	W2250 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1608 00	W2258 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1610 00	N4151 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1611 00	N4143 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1612 00	N4131 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1613 00	N4119 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1614 00	N4109 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1615 00	N4110 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1616 00	N4120 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1617 00	N4132 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1618 00	N4144 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1619 00	W2257 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1620 00	W2251 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1621 00	W2247 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1622 00	W2239 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1623 00	W2227 Pine Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1647 00	N3968 & N3970 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1648 00	N3972 & N3974 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1649 00	N3976 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1649 01	N3978 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1650 00	N3980 & N3982 Shamrock (	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1991	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1651 00	N3984 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1651 01	N3986 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1653 00	N3992 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1991		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1654 00	N3989 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1655 00	N3983 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1656 00	N3977 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2001		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1657 00	N3971 Shamrock Circle	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1658 00	W2229 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2012	SF	N	C		2012		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 1659 00	W2237 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		1980		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1660 00	W2241 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1661 00	W2245 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1662 00	W2249 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1663 00	W2259 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1664 00	W2263 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1665 00	N4280 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1666 00	N4268 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1667 00	N4256 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1668 00	N4244 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1669 00	N4232 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1670 00	N4220 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1671 00	N4208 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	O		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1672 00	N4198 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1673 00	N4195 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1675 00	N4219 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1676 00	N4231 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1988		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1677 00	N4243 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1678 00	N4255 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1679 00	N4267 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1680 00	N4277 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1681 00	N4285 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1682 00	N4291 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1683 00	N4295 Oak Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1684 00	W2264 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1685 00	W2260 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1989		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1686 00	W2256 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1687 00	W2252 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2014	SF	N	C		2014		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 1688 00	W2248 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1690 00	W2234 Chestnut Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1691 00	W2268 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1692 00	W2272 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1693 00	W2280 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1694 00	W2286 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1695 00	W2290 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1696 00	W2289 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1697 00	W2285 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1698 00	W2281 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1699 00	W2273 Blarney Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1700 00	N4319 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1701 00	N4329 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair

090 1702 00	N4337 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1703 00	N4347 Bell Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1704 00	N4366 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1705 00	N4362 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1706 00	N4354 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1994	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1707 00	N4350 Cty Trk E	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2002	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1708 00	N3990 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1998	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1709 00	N3982 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1997	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1710 00	N3976 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1997	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1711 00	N3966 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1712 00	N3952 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1713 00	N3944 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1997	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1714 00	N3932 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1998	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1715 00	N3924 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1994	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1716 00	N3916 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1717 00	N3910 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1718 00	N3900 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1719 00	N3888 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1720 00	N3889 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1721 00	N3897 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1723 00	N3913 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1724 00	N3921 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1725 00	N3929 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1999	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1726 00	N3935 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1998	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1727 00	N3941 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1728 00	N3949 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2000	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1729 00	N3955 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1730 00	N3963 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1731 00	N3969 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1732 00	N3973 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1733 00	N3981 Dublin Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1994	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1734 00	N4147 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		2000	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1735 00	N4133 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2003	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1736 00	N4121 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1997	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1737 00	N4113 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2004	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1738 00	N4110 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2005	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1739 00	N4122 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2002	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1740 00	N4130 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1741 00	N4142 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1994	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1742 00	N4154 Ironwood Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1743 00	N4181 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1744 00	N4165 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		2001	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1745 01	N4159 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1998	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1746 00	N4156 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1747 00	N4162 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C		1998	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1748 00	N4168 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1749 00	N4180 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1750 00	N4192 Birch Trail	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1990	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1751 00	N4202 & N4204 Killarney Ln	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1980s	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1752 00	N4208 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1752 01	N4210 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1753 00	N4214 & N4216 Killarney Ln	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1997	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1754 00	N4220 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1755 00	W1995 Darby Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1756 00	W1987 Darby Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1757 00	W1983 Darby Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1758 00	W1979 Darby Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1759 00	W1976 Darby Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1760 00	W1980 Darby Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1761 00	W1994 Darby Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1762 00	Shed Darby Ct.	UNK	P	N	1"	2008	P	1 1/4"	2020	SF	N	C		2020		Installed after	Y	2008	Visual insp during install or repair	Installed after lead ban	Y	2020	Visual insp during install or repair
090 1763 00	W1967 Tralee Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1764 00	W1959 Tralee Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1765 00	W1951 Tralee Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1766 00	W1968 Tralee Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1767 00	W1974 Tralee Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1768 00	W1980 Tralee Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1769 00	N4242 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1770 00	N4250 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1771 00	N4266 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1772 00	W1977 OCONNOR CT	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1773 00	W1971 OCONNOR CT	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1774 00	W1963 OCONNOR CT	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1776 00	W1960 OCONNOR CT	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1777 00	W1966 OCONNOR CT	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair

090 1778 00	W1974 OCONNOR CT	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1994		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1779 00	W1980 OCONNOR CT	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1780 00	N4276 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1997		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1782 00	N4277 Killarney Ln.	UNK	P	N	1"	2008	P	1 1/4"	2016	SF	N	UNK		Unknown		Installed after	Y	2008	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 1783 00	N4271 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1784 00	N4267 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2005		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1785 00	N4259 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1786 01	N4255 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1786 02	N4253 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2015	SF	N	C		2000s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 1787 00	N4247 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1997		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1787 01	N4245 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1788 00	N4239 & N4241 Killarney Ln	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1789 00	N4233 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1789 00	N4235 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1790 00	N4227 & N4229 Killarney Ln	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1993	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1792 00	N4213 & N4215 Killarney Ln	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1990s	Duplex	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1793 00	N4205 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1793 00	N4207 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1795 00	N4054 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		1990		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1796 00	N4052 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	UNK		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1797 00	N2454 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1980s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1798 00	W2460 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1799 00	W2466 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1800 00	W2469 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1801 00	W2463 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1989		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1802 00	W2459 Pine Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2001		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1803 00	N3611 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1804 00	N3605 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1805 00	N3593 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1998		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1806 00	N3585 Ranch View Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1807 00	N4221 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1808 00	N4223 Killarney Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1996		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1809 00	N3813 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1810 00	N3801 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1811 00	N3793 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1812 00	N3814 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1813 00	N3802 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1999		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1814 00	N3794 Breese Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1817 00	N3989 Washington Ave.	UNK	P	N	1"	2006 - 2009	P	1"	2007	NONRES	N	C		Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1844 00	N3738 Rose Petal Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1845 00	N3735 Rose Petal Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2015	SF	N	C	O	2015		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 1846 00	N3723 Rose Petal Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2017	SF	N	C		2017		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2017	Visual insp during install or repair
090 1847 00	N3711 Rose Petal Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2014	SF	N	C		2014		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 1848 00	W2254 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	CLS	O	1978		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1849 00	N3700 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2019	SF	N	UNK		2019		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2019	Visual insp during install or repair
090 1850 00	N3706 Sharon Rose Ct.	UNK	P	N	1"	2008	P	1 1/4"	2016	SF	N	UNK		Unknown		Installed after	Y	2008	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 1852 00	N3691 Sharon Rose Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1853 00	W2278 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2005		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1854 00	W2285 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1855 00	W2275 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2007		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1856 00	W2269 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1857 00	W2261 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1858 00	W2253 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2000		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1859 00	W2245 Schmidt Rd.	UNK	P	N	1"	2006 - 2009	P	1 1/4"	2016	SF	N	C		2016		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 1860 00	W2246 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2010	SF	N	C	O	2010		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 1861 00	W2250 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2003		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1862 00	W2258 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2001		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1863 00	W2264 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2002		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1864 00	W2270 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	1995		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1865 00	N3659 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1866 00	N3651 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2005		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1867 00	N3643 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2017	SF	N	C		2017		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2017	Visual insp during install or repair
090 1868 01	N3635 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1869 00	N3627 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		1992		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1870 00	N3619 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2001		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1871 00	N3611 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2006		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1872 00	W2262 Raspberry Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2005		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1873 00	W2254 Raspberry Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2006		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1874 00	W2246 Raspberry Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1875 00	W2238 Raspberry Ln.	UNK	P	N	1"	2006 - 2009	P	1"	2016	SF	N	C		2000s		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 1876 00	W2239 Rock Garden Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2009	SF	N	C	O	2010		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1877 00	W2247 Rock Garden Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	Unknown		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1878 00	W2246 Rock Garden Ct.	UNK	P	N	1"	2006 - 2009	P	1"	2011	SF	N	C		2011		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 1880 00	W2241 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2004		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1881 00	W2249 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	O	2003		Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair

090 1882 00	W2257 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C	O	2001	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1883 00	W2265 Olive Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2003	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1884 00	N3646 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2015	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 1885 00	N3636 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C	O	2003	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1886 00	N3626 Rose Garden Way	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	C		2005	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1912 00	N3829 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1960s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1913 00	N3843 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1914 00	N3849 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	Y	C		2005	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1915 00	N3857 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	C		2005	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1916 00	N3865 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1970s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1917 00	N3869 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	2005	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1918 00	N3879 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		2005	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1919 00	N3890 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C	O	Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1920 00	N3882 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1921 00	N3876 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C	O	1990s	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1922 00	N3864 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	N	C	O	Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1923 00	N3854 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2006	SF	Y	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1924 00	N3846 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2008	SF	N	UNK		Unknown	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1925 00	N3840 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	Y	C	O	2003	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1926 00	N3836 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	C		2004	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1927 00	N3810 Mc Hugh Rd.	UNK	P	N	1"	2006 - 2009	P	1"	2007	SF	N	CLS	O	1978	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1958 00	N3612 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2007	SF	N	C		2006	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1959 00	N3608 Scenic Ln.	UNK	P	N	1"	2004	P	1 1/4"	2008	SF	N	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1960 00	N3600 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2008	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1961 00	N3592 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2010	SF	N	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 1962 00	N3586 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2010	SF	N	C		2010	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 1963 00	N3580 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2014	SF	N	C		2013	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 1964 00	N3572 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2008	SF	N	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1965 00	N3564 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2008	SF	Y	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1966 00	W2450 Western Dr.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1967 00	W2442 Western Dr.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2007	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1968 00	W2436 Western Dr.	UNK	P	N	1"	2004	P	1"	2007	SF	N	C		2004	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1969 00	W2428 Western Dr.	UNK	P	N	1"	2004	P	1"	2008	SF	N	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1970 00	W2420 Western Dr.	UNK	P	N	1"	2004	P	1"	2009	SF	N	C		2009	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1971 00	W2412 Western Dr.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2004	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1972 00	W2404 Western Dr.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1974 00	N3536 Range Ct.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1975 00	N3528 Range Ct.	UNK	P	N	1"	2004	P	1"	2006	SF	Y	C		2009	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1976 00	N3520 Range Ct.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2011	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1977 00	N3516 Range Ct.	UNK	P	N	1"	2004	P	1"	2008	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1978 00	N3519 Range Ct.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2006	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1979 00	N3525 Range Ct.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1980 00	W2431 Western Dr.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1981 00	W2437 Western Dr.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2001	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1982 00	W2447 Western Dr.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1983 00	N3538 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2007	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1984 00	N3522 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2013	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1985 00	N3512 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2008	SF	N	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 1986 00	N3508 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2014	SF	N	C		2014	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 1987 00	N3507 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	NONRES	N	C		2006	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1988 00	N3513 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1989 00	N3521 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2012	SF	N	C		2012	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 1990 00	N3527 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2009	SF	N	C		2009	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1991 00	N3539 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1992 00	N3547 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2009	SF	N	C		2009	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1993 00	N3555 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2009	SF	N	C		2009	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 1994 00	N3565 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2010	SF	Y	C		2011	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 1995 00	N3569 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2005	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1996 00	N3577 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2013	SF	N	C		2014	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 1997 00	N3585 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2010	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 1998 00	N3591 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2007	SF	Y	C		2008	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 1999 00	N3599 Scenic Ln.	UNK	P	N	1"	2004	P	1"	2006	SF	N	C		2004	Installed after	Y	2004	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2001 00	W1951 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2006	SF	N	C		2007	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2002 00	W1941 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2006	SF	N	C		2006	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2003 00	W1935 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2006	SF	N	C		2009	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2005 00	W1925 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2013	SF	N	C		2013	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 2006 00	W1909 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2006	NONRES	N	C		2006	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2007 00	W1908 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2011	SF	UNK	UNK		Unknown	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2008 00	W1918 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2006	SF	N	C		2006	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2009 00	N4286 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2007	SF	N	C		2008	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2010 00	N4294 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2010	SF	N	C		2010	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 2011 00	N4302 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2016	SF	N	C		2000s	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 2012 00	N4312 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2007	SF	N	C		2007	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2013 00	N4316 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2006	SF	N	C		2006	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2014 00	N4327 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2014	SF	N	CLS	O	2015	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair

090 2018 00	N4295 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2006	SF	N	C		2006	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2020 00	W1924 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2006	SF	N	C		2005	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2006	Visual insp during install or repair
090 2021 00	W1946 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2009	SF	N	C		2013	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 2022 00	W1952 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2007	SF	N	C		2007	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2065 00	W1958 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1 1/4"	2010	SF	N	C		2010	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 2066 00	W1966 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2008	SF	N	C		2008	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 2067 00	W1976 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2008	SF	N	C		2008	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 2068 00	W1980 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2008	SF	N	C		2009	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 2069 00	W1992 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2010	SF	N	C		2010	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 2070 00	W2012 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2008	SF	N	C		2009	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair
090 2071 00	W2020 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2007	SF	N	C		2007	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2072 00	W2026 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2013	SF	N	C		2012	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 2073 00	W2073 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2011	SF	N	C		2012	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2074 00	W2044 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2015	SF	N	C		2015	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 2075 00	N4357 Kylea Ct.	UNK	P	N	1"	2005	P	1"	2013	SF	N	C		2012	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 2076 00	N4341 Kylea Ct.	UNK	P	N	1"	2005	P	1"	2014	SF	N	C		2014	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 2077 00	N4338 Kylea Ct.	UNK	P	N	1"	2005	P	1 1/4"	2015	SF	N	C	O	2015	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 2078 00	N4344 Kylea Ct.	UNK	P	N	1"	2005	P	1"	2015	SF	Y	C		2015	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 2079 00	N4348 Kylea Ct.	UNK	P	N	1"	2005	P	1"	2011	SF	Y	C		2011	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2080 00	W2066 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2010	SF	N	C		2015	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 2081 00	W2086 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2011	SF	N	C		2011	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2082 00	W2092 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2007	SF	UNK	C		2006	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2084 00	N4313 Serenity Ridge Ct.	UNK	P	N	1"	2005	P	1"	2012	SF	UNK	C		2013	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 2086 00	W2069 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2011	SF	N	C		2012	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2087 00	W2063 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2011	SF	N	C		2010	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2088 00	W2057 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2012	SF	N	C		2011	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 2089 00	W2045 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2013	SF	N	C		2013	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 2090 00	W2039 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2012	SF	N	C		2012	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 2091 00	W2027 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2007	SF	N	C		2008	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2092 00	W2019 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2011	SF	N	C		2011	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2093 00	W2013 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2012	SF	N	C		2012	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 2094 00	W2009 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2015	SF	N	O		2015	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 2095 00	W1997 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2016	SF	N	C		2016	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 2096 00	W1993 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2010	SF	N	C		2011	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2010	Visual insp during install or repair
090 2097 00	W1989 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2016	SF	N	C		2017	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2016	Visual insp during install or repair
090 2098 00	W1977 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2015	SF	N	C		2016	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2015	Visual insp during install or repair
090 2099 00	W1969 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2007	SF	N	C		2008	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2100 00	W1961 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2007	SF	N	C		2008	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2007	Visual insp during install or repair
090 2102 00	W2095 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1 1/4"	2017	SF	N	C		2018	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2017	Visual insp during install or repair
090 2103 00	W2091 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2014	SF	N	C		2015	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2014	Visual insp during install or repair
090 2104 00	W2087 Finnigans Ridge Ln.	UNK	P	N	1"	2005	P	1"	2011	SF	N	C		2011	Installed after	Y	2005	Visual insp during install or repair	Installed after lead ban	Y	2011	Visual insp during install or repair
090 2106 00	W1992 Industrial Dr. UnitB	UNK	P	N	2"	2006 - 2009	P	1"	2009	NONRES	N	C	O	Unknown	Klink Properties - Mu	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 2107 00	W1970 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	1"	2009	NONRES	N	C		Unknown	Klink Properties - Mu	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2009	Visual insp during install or repair
090 2108 00	W1944 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	2"	2012	NONRES	N	C	O	2010	CCW Properties - Multiple Buildings							
090 2108 00	W1944 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	2"	2012	NONRES	N	C	O	2017	CCW Properties - Multiple Buildings							
090 2108 00	W1944 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	2"	2012	NONRES	N	C	O	2017	CCW Properties - Multiple Buildings							
090 2108 00	W1944 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	2"	2012	NONRES	N	C	O	2010	CCW Properties - Mu	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 2109 00	W1920 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	1"	2012	NONRES	N	C		2012	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 2110 00	W1925 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	1"	2012	NONRES	N	C		2012	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2012	Visual insp during install or repair
090 2111 00	W1941 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	1"	2013	NONRES	N	O		2019	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2013	Visual insp during install or repair
090 2112 00	W1967 Industrial Dr. B	UNK	P	N	2"	2006 - 2009	P	2"	2017	NONRES	N	O		2017	Wifl Investments - Cc	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2017	Visual insp during install or repair
090 2113 00	W1989 Industrial Dr.	UNK	P	N	2"	2006 - 2009	P	1 1/2"	2008	NONRES	N	C	O	2008	Installed after	Y	2006 - 2009	Visual insp during install or repair	Installed after lead ban	Y	2008	Visual insp during install or repair